


ViewScan

a data acquisition software
for viewing the quality of crankshafts,
camshafts, gears, valves, bearings...



TAKE ADVANTAGE OF THE MANY USEFUL FEATURES OF THE VIEWSCAN

- Collect and analyze data from Rollscan, Stresscan and μ Scan
- View and print results while you make new measurement
- View one or up to 200 plots at the same time
- View the results as a 3-dimensional polysurface
- Make templates to repeat measurements
- Set reject criteria and alarm limits
- Export data for analysis with other programs
- Use for real-time rejection checking
- Use for Statistical Process Control
- Automate start and stop events
- etc.

MINIMUM SYSTEM REQUIREMENTS

- Microsoft Windows operating system (Windows NT 4.0, Windows 2000 pro or Windows XP recommended)
- Personal computer with Pentium compatible microprocessor (200 MHz or higher recommended)
- 800 x 600 (SVGA) or higher resolution video adapter (minimum 256 colors)
- Memory of 16 MB of RAM (64 MB recommended)
- At least 10 MB hard disk space
- Mouse or other pointing device



www.stresstech.fi

Stresstech Oy
Tikkutehtaantie 1
FIN-40800 VAAJAKOSKI, Finland
Tel +358-14-333 000, fax +358-14-333 0099
e-mail: info@stresstech.fi
www.stresstech.fi

American Stress Technologies, Inc.
267 Kappa Drive
Pittsburgh, PA 15238, USA
Tel +1-412-963 0676, fax +1-412-963 7552
e-mail: info@ASTresstech.com
www.astresstech.com

Stresstech GmbH
Bahnhofstrasse 3
D-56457 WESTERBURG, Germany
Tel +49-2663-915 00, fax +49-2663-915 055
e-mail: info@stresstech.de
www.stresstech.de



stresstech group

ViewScan



stresstech group

ViewScan



stresstech group

ViewScan



stresstech group

ViewScan